




Fatigue curves-smooth specimens



Fatigue curves-notched specimens



Smooth



N90 ( $2\alpha=90^\circ$ )



N30 ( $2\alpha=30^\circ$ )

